

# PRE3206

External IP66 Twilight switch

Wiring diagram page 1 of 1



Cleverly simple  
control of energy.




Where possible mount the sensor as high as possible on a north facing vertical surface.

Ensure that all cable entry to the enclosure is via suitable cable glands and seal with silicone sealant.

If it is necessary to screw through the rear of the enclosure ensure that any holes are covered with the caps provided and sealed with silicone sealant where appropriate.

Rear view of Sensor



Due to our policy of continuous improvement, we reserve the right to change specifications without notice. All information was correct at time of when this product file was produced - July 2021